


Looking downstream (south) at power house and dam. Existing



Looking downstream (south) at new dam, new powerhouse (left) and old powerhouse (right). August 1928



Top of dam and former impoundment area. Existing



Top of dam and impoundment. Before 1928



Looking upstream at dam and powerhouse. Existing



Looking west at dam and powerhouse. Date unknown (after 1928)



Looking east at dam, apron and fish ladder.



DAM, AFRON & FISH LADDER



DOWAGIAC CREEK POWER HOUSE

Dam located upstream of existing dam. Before 1928





Looking west at dam, manager's house and Pucker Street bridge. 1897



Abandoned spillway with powerhouse on left. Existing
This was the location of the mill race in 1828 and the powerhouse with turbine from at least 1897 until 1928.



Looking downstream at east and west concrete walls. Existing



Looking upstream at east concrete wall and spillway. Existing




Looking west, old foundation of the brick structure pictured below. Existing



Looking upstream at abandoned spillway/old foundation of 1897 powerhouse (old powerhouse foundation pictured below). Existing







FOUNDATIONS


NILES CITY POWER PLANT (1895,1928) Pucker St. at Dowagiac Creek Niles Cassopolis 16.562097.4634080 Berrien

On August 14, 1895 the newly-formed Niles Board of Public Works took over the Niles Electric Company hydroelectric plant located on Dowagiac Creek north of Niles. The dam and generating station located at this site, powered by horizonal water wheels, supplied Niles with electricity until they were replaced in 1928 by the present dam and powerhouse. The only part of the 1895 installation still extant are portions of the exit racewyas leading from the old powerhouse. The 1928 powerhouse, 10 feet by 15 feet, is a brick structure resting on a concrete foundation. The adjoining spillway dam is 60 feet long and is equipped with six radial (tainter) gates.

[Stevens, Howard G., Niles Board of Public Works, Seventy-Fifth Anniversary Report (Niles, 1970)]

Foundations Before 1928







Powerhouse and dam with Pucker Street bridge in backgound. Date unknown, but after 1928



Powerhouse with Manager's house and old brick structure. Date unknown, but after 1928



Pucker Street Bridge. Existing



Old dam and Pucker Street Bridge. 1924


Old dam and Pucker Street Bridge. August 1928

Inside Powerhouse. Existing












Inside powerhouse, bathroom and office showing significant damage. Existing



Inside Lower Powerhouse. Existing

The lower powerhouse was inspected by Jeff Dunlap, a registered building inspector. A confined space entry was needed to take these photographs. No evidence of a previous dam structure was found during the investigation.





West wall at Penstoo door/gate. Seepage through door is evident. No pre-current dam structure found.